



## DEBRİYAJ RULMANLARI

| SKF NO:  | ARAÇ     | BRUT<br>€ |
|----------|----------|-----------|
| VKC 2045 | Mercedes | 13,51     |
| VKC 2065 | Volvo    | 13,85     |
| VKC 2080 | Renault  | 10,13     |
| VKC 2091 | VW       | 19,94     |
| VKC 2095 | Fiat     | 7,71      |
| VKC 2108 | PSA      | 9,45      |
| VKC 2115 | PSA      | 16,37     |
| VKC 2115 | Fiat     | 16,37     |
| VKC 2120 | BMW      | 22,94     |
| VKC 2125 | VW       | 26,17     |
| VKC 2144 | Ford     | 10,13     |
| VKC 2151 | BMW      | 26,99     |
| VKC 2161 | Ford     | 13,51     |
| VKC 2163 | Ford     | 11,71     |
| VKC 2164 | Ford     | 12,14     |
| VKC 2168 | Fiat     | 10,40     |
| VKC 2183 | Fiat     | 14,18     |
| VKC 2186 | Opel     | 10,23     |
| VKC 2189 | Renault  | 16,37     |
| VKC 2190 | Renault  | 21,59     |
| VKC 2191 | Renault  | 10,66     |
| VKC 2193 | PSA      | 9,03      |
| VKC 2195 | VW       | 9,45      |
| VKC 2202 | Mercedes | 12,81     |
| VKC 2213 | Opel     | 12,01     |
| VKC 2215 | Opel     | 9,81      |
| VKC 2216 | PSA      | 8,22      |
| VKC 2216 | Fiat     | 8,22      |
| VKC 2216 | Rover    | 8,22      |
| VKC 2217 | Rover    | 53,33     |
| VKC 2218 | Saab     | 14,18     |
| VKC 2220 | VW       | 8,17      |
| VKC 2238 | Daewoo   | 10,11     |
| VKC 2238 | Opel     | 10,11     |
| VKC 2239 | PSA      | 12,99     |
| VKC 2239 | Fiat     | 12,99     |
| VKC 2241 | VW       | 12,12     |
| VKC 2433 | Renault  | 12,14     |
| VKC 2433 | Volvo    | 12,14     |
| VKC 2501 | Fiat     | 12,55     |
| VKC 2516 | PSA      | 8,68      |
| VKC 2519 | VW       | 12,14     |
| VKC 2519 | Mercedes | 12,14     |
| VKC 2523 | PSA      | 9,14      |
| VKC 2523 | Fiat     | 9,14      |
| VKC 2535 | Lada     | 11,02     |
| VKC 2537 | PSA      | 9,88      |
| VKC 2537 | Fiat     | 9,88      |
| VKC 2538 | Rover    | 11,54     |
| VKC 2542 | PSA      | 27,69     |

| SKF NO:  | ARAÇ       | BRUT<br>€ |
|----------|------------|-----------|
| VKC 2542 | Fiat       | 27,69     |
| VKC 2546 | Ford       | 17,54     |
| VKC 2547 | Ford       | 16,86     |
| VKC 2548 | Ford       | 16,37     |
| VKC 2601 | VW         | 9,81      |
| VKC 2601 | Ford       | 9,81      |
| VKC 2616 | PSA        | 10,72     |
| VKC 3500 | Nissan     | 10,82     |
| VKC 3502 | Toyota     | 11,01     |
| VKC 3505 | Opel       | 12,66     |
| VKC 3507 | Toyota     | 14,93     |
| VKC 3508 | Honda      | 24,41     |
| VKC 3509 | Suzuki     | 11,22     |
| VKC 3515 | Mitsubishi | 18,69     |
| VKC 3524 | Daihatsu   | 43,87     |
| VKC 3542 | Honda      | 26,37     |
| VKC 3551 | Nissan     | 16,86     |
| VKC 3552 | Mitsubishi | 28,38     |
| VKC 3554 | Opel       | 27,26     |
| VKC 3555 | Nissan     | 28,34     |
| VKC 3556 | Toyota     | 23,34     |
| VKC 3559 | Mitsubishi | 45,37     |
| VKC 3560 | Nissan     | 22,94     |
| VKC 3564 | Suzuki     | 31,65     |
| VKC 3565 | Nissan     | 29,02     |
| VKC 3567 | Suzuki     | 18,45     |
| VKC 3568 | Mazda      | 24,31     |
| VKC 3573 | Hino       | 31,65     |
| VKC 3577 | Honda      | 21,66     |
| VKC 3578 | Daihatsu   | 31,65     |
| VKC 3579 | Mitsubishi | 26,07     |
| VKC 3581 | Nissan     | 24,69     |
| VKC 3582 | Subaru     | 36,02     |
| VKC 3584 | Toyota     | 41,17     |
| VKC 3592 | Mitsubishi | 33,75     |
| VKC 3598 | Nissan     | 34,42     |
| VKC 3600 | Mazda      | 23,75     |
| VKC 3602 | Mazda      | 28,03     |
| VKC 3603 | Honda      | 37,12     |
| VKC 3605 | Honda      | 26,99     |
| VKC 3606 | Opel       | 35,77     |
| VKC 3607 | Mazda      | 24,98     |
| VKC 3609 | Mazda      | 30,39     |
| VKC 3610 | Nissan     | 19,59     |
| VKC 3611 | Nissan     | 35,77     |
| VKC 3612 | Nissan     | 27,67     |
| VKC 3613 | Subaru     | 39,52     |
| VKC 3615 | Toyota     | 30,20     |
| VKC 3616 | Toyota     | 32,40     |
| VKC 3617 | Honda      | 26,37     |



## DEBRİYAJ RULMANLARI

| SKF NO:  | ARAÇ       | BRUT<br>€ |
|----------|------------|-----------|
| VKC 3617 | Rover      | 26,37     |
| VKC 3620 | Mitsubishi | 76,15     |
| VKC 3620 | Subaru     | 76,15     |
| VKC 3622 | Toyota     | 26,37     |
| VKC 3623 | Suzuki     | 19,18     |
| VKC 3625 | Toyota     | 39,77     |
| VKC 3626 | Toyota     | 25,66     |
| VKC 3627 | Toyota     | 61,29     |
| VKC 3628 | Toyota     | 39,84     |
| VKC 3640 | Toyota     | 34,42     |
| VKC 3645 | Toyota     | 54,66     |
| VKC 3654 | Honda      | 41,85     |
| VKC 3660 | Subaru     | 29,71     |
| VKC 3666 | Hyundai    | 47,93     |
| VKC 3667 | Suzuki     | 28,34     |
| VKC 3668 | Daihatsu   | 48,22     |
| VKC 3671 | Toyota     | 32,35     |
| VKC 3673 | Hyundai    | 23,72     |
| VKC 3674 | Hyundai    | 25,07     |
| VKC 3675 | Daewoo     | 23,62     |
| VKC 3678 | Suzuki     | 44,15     |
| VKC 3684 | Suzuki     | 21,21     |
| VKC 3686 | Toyota     | 34,42     |
| VKC 3688 | Toyota     | 31,82     |
| VKC 3737 | Nissan     | 31,20     |

| SKF NO: | ARAÇ | BRUT<br>€ |
|---------|------|-----------|
|---------|------|-----------|